

SUITE 306, GATEWAY CENTRE II 4TH & STATE AVENUE KANSAS CITY, KS 66101 PHONE: 913-621-6240

Site: Proce Martha
ID#: 100980633069
Break:
Other:
10-19-83
078D

TO:

William Keffer, Chief, EP&R/ENSV

October 19, 1983

FROM:

Michael G. Clemons, Region VII TAT

TAT-07-F-00214

SUBJECT:

Sampling of material located in a 12,000 gallon gasoline storage tank

Holden, Missouri TDD #07-8310-12

At 0800 hours on October 13, 1983, the Environmental Protection Agency (EPA) dispatched the Region VII Technical Assistance Team (TAT) to Holden, Missouri to sample a gasoline storage tank whose contents caused 14 people to be admitted to St. Joseph's Hospital for treatment. Michael Clemons, Russ Krohn and George Hess responded to the Holden, Missouri site.

The tank was located in a PCB drum storage warehouse of the Carolan Company, located at 500 West McKissock, Holden, Missouri.

The TAT team arrived on scene at 0945 hours. After conferring with Holden Police Chief Ron Flippin and Johnson County Sheriff, Charles Norman, the TAT entered the warehouse with Dwight Thomas, Head of Research and Development with the Carolan Company, and Tony Lerda, Missouri Department of Natural Resources (MDNR).

The recently acquired gasoline storage tank had been pushed into the warehouse for cleaning before the Carolan Company put it into use. On October 12, 1983, Terry Bryant, an employee of the Carolan Company, was lowered into the tank by a rope. Bryant, reportedly outfitted with a full face respirator and organic vapor cartridges and a plastic rainsuit, immediately became disoriented, lost hold of the rope and passed out. Rescue workers picked up Bryant who had been lying in approximately 4-5 inches of sludge and liquid material.

Bryant, the rescue workers, and the ambulance personnel who came in contact with the liquid from the tank, exhibited one or more of the following acute exposure symptoms:

Blistering/rash/red splotches Nausea/white foamy vomit Severe stomach cramps/diarrhea Headache Muscle cramps Stiff joints



According to Mr. Thomas, the only material ever stored in the tank was premium, leaded gasoline. He had purchased the tank from the Dyer Oil Company, located at 801 Southeast 291 Highway, Lee's Summit, Missouri, 816/524-3466.

The TAT observed the tank in question. The tank was cylindrical in shape with a conical top. It measured approximately 18 feet tall and 12 feet in diameter with a 12,000 gallon capacity. The only entrance to the tank was a manhole on the top cone-shaped surface. The TAT, outfitted in level B, lowered a weighted-bottle sampler from the top manhole in an attempt to obtain a sample from a small pool of liquid still floating on the sludge, but was unsuccessful. The TAT then lowered the sampling dredge and obtained a sample from the sludge (sample #AKO101).

Preliminary readings from inside the tank were as follows: 130 ppm of organic vapors according to the Hnu photoionization detector as calibrated to benzene with an 11.7 eV probe. Oxygen readings were 20% and vapors read 15% of the Lower Explosive Limit (LEL) as read by the Edmont Ecolyzer 0₂/explosimeter. The explosimeter is calibrated to methane.

The material sampled had a pH of 2.5 as taken with Panpeha pH indicator strips. The Carolan Company took a mass spectrum reading of material checking for Polychlorinated Biphenyls (PCB's) on October 12, 1983, after the incident occurred. They reported no PCB's (see data sheet in Appendix) and a pH of 6.5-7.5. Mr. Thomas asked for a split sample (see receipt in Appendix).

A meeting was then held with Holden city officials and the TAT concerning the tank incident and the operation of the Rose Chemical Company PCB destruction facility located in the same complex. The Rose Chemical Company and the Carolan Company are apparently owned by the same person. There was some concern exhibited by the city officials of the integrity of the companies in light of their past spill history as well as legal liabilities posed on the City since the City leases the property to the two companies.

The TAT gave the Holden city officials the number of Leo Alderman, who is in EPA's Toxics and Pesticides Branch (TOPE), for further assistance with their questions concerning the PCB facility.

The Holden officials were also concerned about their immediate health hazards after having been exposed to the material from the tank. The TAT contacted Edward Skowronski, EPA's Region VII representative from the Center for Disease Control (CDC) and informed him of the situation through William Keffer, Chief, EPA/EP&R. The TAT left Holden at 1530 and rushed the sample to EPA's Region VII laboratory for analysis. EPA's Emergency Planning and Response team's involvement in the incident is closed at this point.

The Occupational Safety and Health Administration (OSHA) had been contacted and was in the process of inspecting the facility while the TAT was on scene.

Michael D. Clansons

MICHAEL G. CLEMONS Region VII TAT

Reviewed by David N. Cargo

Region VII TATL

Attachments

MGC/dm

OFFICIAL CONTACTS ON SCENE

TONY LERDA MDNR 615 East 13th Street Kansas City, MO 64106 816/274-6675

CHIEF DAY Holden, Missouri Fire Dept. 816/732-5527

WALTER C. DENNIS OSHA 12th Floor, 1150 Grand Ave. Kansas City, MO 64106 816/374-2756 CHIEF FLIPPIN
Holden, Missouri Police Dept.
816/732-4154

DWIGHT THOMAS
Head of Research & Development
Carolan Company
500 West McKissock
Holden, MO 64040
816/732-4117

CHARLES NORMAN
Johnson County, Missouri Sheriff
816/782-5000

MEETING ATTENDEES - 10/13/83 - HOLDEN, MISSOURI

Harold Fisher, Johnson County Sheriff Charlie Norman, Johnson County Sheriff Mike Droege, Holden Fire Department Raymond Dacy, Holden Fire Chief Mike Guddle, Holden Fire Department Sherry Kane, Holden Ambulance Director Glen Hite, Holden Police Department Linda Leavy, Holden Police Department Ron Flippin, Holden Police Department Don Hancock, Mayor of Holden Roy Sturgis, Councilman Jim Williams, Councilman

		Region	VII
		Date	10-13-83
		TDD#	
	SAFETY PLAN		• · · · · · · · · · · · · · · · · · · ·
A Incident	Description		
1.	Location Carolan Co.	2. Date	10-13-83
	500 W. MCKISSOCK		
	Holden, Mo 64040		
3. ,	Type: Spill Fire HW	Site // Of	ther 12,000 tank
4.	Status Reg. DI TAT & EPER/EPA	Portun closed	
.5.	Response Objectives Sample Mater	al in tank	
	for	miterial Krown to Partial /_/	he in tank
6.	Background Review: Complete / Com	Partial //	
7.	Hazard Level: High // Moderate Inhalation // Ingestion //	LowContact	Unknown // External //
8.	Site Plan/Sketch Attached Yes	No 🗹	
9.	Background Material attached Yes	☑ No ☑	
B. <u>Material</u>	<u>Pescription</u>		
1.	Type: Liquid 🗹 Solid 🔟	Sludge 🗹	Vapor/Gas 🗹
2.	Chemical Name/Class Premum leaded	CASOLINE & UN	KNOWN - POSINY TETRATA
3.	Characteristics: Corrosive // Toxic //	ignitable 📈	Volatile 🗹 Biological Agent
4.	Toxicity: TLV	IDLH	
5.	Special Hazards Apparently breakdown or	f chemical or un	known chem involved
	Acute Exposure Symptoms blistering,		
	Champs, Muscle communes, distributes,		_
	to land possoning, - Symptoms Exhibited	Dy 14 Affected pe	ople.
			•

SMG:ss 11/24/82

	1.	size 12,00 gal upright TANK -Approximately 18'x 12'
	2.	Surrounding Population IN toval community of Approx 2,089 people
	3.	Buildings/Homes Several wavehouse & PCB/Chemun fairlibies
	4.	Topography N/A
-		Receiving Waters
	6.	Weather
	7.	Unusual Features 14 people who came in physical contact with mutural tank were hospitalized with the recorded symptoms, Tank bested in wome home
	8.	Site History Boy was lowered into tank to clean it & passed out. Rescuers of by obtained recorded symptoms from contact with material. Only reported substantin tank for last 20 years was premium leaded gasoline.
D. Perso	nnel	Protection
	•	Entry Level of Protective clothing: A // B // C // D //
-		
	2.	If not B, why?
	3.	Site Instrument Readings:
		% 02 20% in tauk % LEL 3% in tauk Radioactivity HNU 120 ppm at drain plue OVA Other pH 2.5
	4.	Was protective level up or downgraded: Yes // No /V/ Up or Down graded to: A / / B / / C / / D // Why
		Actual Change:
	5.	Respirator Protective Equipment:
٠.		SCBA Canister Type Ultra Twin Cartridge Type Dust Mask
•	6.	Protective Clothing:
		And Sut (AVC) uton abus
		Neoprene Boots Nue withile gloves
		Burgual Ak glovas

C. <u>Site Description</u>

. 7.	Field Monitoring Equi	pment and Ma	terials	٠	٠.	
•	Edmont EcolyzER	sample o	redze	. <u>-</u>	·	· · · · · · · · · · · · · · · · · · ·
	Hnu			_		· ·
	heighted bottle simpler			. <u>-</u>		
<u>Deconta</u>	mination Procedures				-	
- 1.	Attach sketch showing Support Zone and numer Material used place					
2.	For each decontaminat on an attachment page	ion station	note proce	dure an	d materials (needed
General	Information		•			
1.	Team members			•		·
	M. Ke Clemons Tes	m Leader	·			
•	Russ Knohn					
	George Ideas	<u>.</u>	-			
2.		or <u>Cle</u> n	~~:			
		· · · · · · · · · · · · · · · · · · ·				
Emergen	cy Information				• *	
1.	Have nearby people be If yes ever how large				No //	
2.	First Aid Instruction	See OAfa	Sheets			_
3.	Sources of help	Nam e		Town	Phone	Noti
	Fire Police	i	1	HOLDEN	916/732-5527 816/732-4154	On some
٠.	Ambulance Hospital タ、ガ Poison Informatio	on on	. 1	(c'wo A	ON Scene 914 /942-4400	Dybelone Dybelone
	Airport Heliport & Sec Site Telephone Nearest Telephone	yh Iskeline	_	forden forden	Thru Ambulance	Dyblone

	4. Emergency Telephone Numbers		
	WESTON Hot Line WESTON NPO P. B. Lederman - NPM	215-524-1925 or 1926 215-431-0797 or 0798 or 692-3030 201-665-0359 (Home)	
	S. M. Gertz - HSO Medical Emergency EPA ERT Emergency Chemtrec	215-667-5461 (Home) 513-421-3063 (National Service) 201-321-6660 800-424-9300	
-	Central Disease Contro National Pesticide Medical Emergency	01 404-329-3311 (day) 404-329-3644 (day) 404-329-36	
·			
		Prepared by Mte Plenne Date 10-13-53	- - `-
/r 1100	U	Date 10-24-83	d Novo
(FOT HSU	Use Only)	i	
	Reviewed and Comments	7	- -
	Action Required? Yes //	No // If yes, what action	- -
. •	Followup carried out? Date		<i>-</i> -
	•	S. O. Signature Date	-

6.10 Odor Threshold: 0.25 ppm

GASOLINES: AUTOMOTIVE

Watery Equid Colories to pale brown or pink Casoline odor Ploats on water. Planuasble, irritating vapor is produced. Stop discharge II possible. Keep people away. Shut off ignition sources and call life department. Sky apprind and use water spray to "knock down" vapor. Isolate and remove discharged material. Notify local health and polition control agencies. FLAMMABLE. Fleshbeck slong FLASHABLE. Flashback long vapor trall may occur. Vipor may explode if ignited in an enclosed area. Extinguish with dry disminist, foam, or carbon dioxide. Water may be ineffective on fire. Cool exposed containers with water. Fire CALL FOR MEDICAL AID. VAPOR Irritating to eyes, now and throat. If inhaled, will cause dizziness, beadeache, difficult breathing or loss of correctorees. More to fresh sir. ** handfilm has stopped, give artificial respiration. LIQUID britating to skin and eyes. Hywellowed, will cause nauses or vomiting. Kennove contaminated clething and shees. Figure 1. The state of the st Exposure OF MINT. DO NOT INDUCE VONITTING. HARMFUL TO AQUATIC LIPE IN VERY LOW CONCENTRATIONS. HARMER to thoreline. May be dangerous if it enters water intaken. Notify local health and wildlife officiels. Notify operators of nearby water intaken. Water Pollution 2. LABELS 1. RESPONSE TO DISCHARGE ree Methods Handback, CO 446-G Issue warning-high flammability Evacuate ar Disperse and flush 3. CHEMICAL DESIGNATIONS 4. OBSERVABLE CHARACTERISTICS 3.1 Synonyme: Motor spirit 4.1 Physical State (as shipped): Liquid Petrol 4.2 Color: Colorless to brown 3.2 Coast Quard Compatibility Classification 4.3 Oder: Gasoline Petroleum oils ical Formula: (Mixture of hydrocar **3.4** INCO/United Nations Numerical Designation: 3.1/1203. 5. HEALTH HAZARDS 5.1 Personal Protective Equipment: Protective goggles, gloves 5.2 Symptoms Following Exposure: Erritation of mucous membranes and stimulation followed by depression of central nervous system. Breathing of vapor may also cause dizziness, headache, and incoordination or, in more severe cases, a nesthesia, coma, and respiratory arrest. If fiquid enters lungs, it will cause severe irritation, coughing, pagging, pulmonary edema, and, later, signs of bronchopneumonia and pneumonitis. Swallowing may cause irregular heartbeat. ment for Exposure: INHALATION: maintain respiration and administer oxygen; enforce bed rest if liquid is in lengs. INGESTION: do NOT induce vomiting; stomach should be lavaged (by doctor) if appreciable quantity is swallowed, EYES; wash with copious quantity of water. SKIN: wipe off and wash with soap and water. 5.4 Texicity by Inhelation (Threshold Limit Value): No single TLV applies. 5.5 Short-Torm Inhalation Limits: 500 ppm for 30 min. 8.8 Toxicity by Ingestion: Grade 2: LD= 0.5 to 5 g/Ls. 8.7 Late Toxicity: None 8.8 Vapor (Gos) Brittont Cheroctoristics: Vapors cause a slight smarting of the eyes or respiratory system if present in high concentrations. The effect is temporary. 8.9 Liquid or Solid irritant Characteristics: Minimum hazard. If spilled on clothing and allowed to remain, may cause smarting and reddening of the skin.

6. FIRE HAZARDS 6.1 Flosh Point: -36°F.C.C. 6.2 Flormable Limit in Air: 1.4%—7.4% 6.5 Fire Extinguishing Agenta: Foam, carbon dioxide, dry chemical 6.4 Fire Extinguishing Agenta Not to be Used: Water may be ineffective 6.5 Special Nazards of Combustion Products: None 6.6 Behavior in Fire: Vapor is heavier than air and may travel considerable distance to a source of ignition and flash back. 6.7 Ignition Temperature: 833°F 6.8 Electrical Hazard: Class I, Group D 6.9 Burning Rate: 4 mm/min. 7. CHEMICAL REACTIVITY 7.1 Reactivity with Water: No reaction 7.2 Reactivity with Common Materials: No reaction 7.3 Stability During Transport: Stable 7.4 Neutralising Agents for Acids and Caustics: Not pertinent 7.5 Polymerization: Not pertinent 7.6 Inhibitor of Polymerization: Not pertinent	8. WATER POLLUTION 8.1 Aquatic Texicity: 90 ppm/24 br /juvenile American shad/ TLm/fresh water 91 mg/l/24 br /juvenile American shad/ TLm/saft water 8.2 Waterlowl Toxicity: Date not available 8.3 Blological Orygen Demend (BOD): 8%, 5 days 8.4 Food Chain Concentration Potential: Nonc 9. SELECTED MANUFACTURERS 1. Exon Co. 20 Rocksfeller Plaza New York, N. Y. 10020 2. Shell Oil Co. 1 Shell Plaza Houston, Texas 77001 3. San Oil Co. 51. Davids, Pa. 19087 10. SHIPPING INFORMATION 10.1 Grades or Purkly: Various octane vatings; military specifications 10.2 Storage Temperature: Ambient 10.3 Insert Atmosphere: No requirement 10.4 Venting: Open (flame arrester) or pressure-vacuum
IL HAZARD ASSESSMENT CODE (Nos Hazard Amesonment Handbook, Cop age 4) A-T-U-V-W	13. PHYSICAL AND CHEMICAL PROPERTIES 13.1 Physical State at 15°C and 1 atm: Liquid 13.2 Molecular Weight: Not partiness 13.3 Boiling Point at 1 atm: 140—390°F
12. HAZARD CLASSIFICATIONS 12.1 Code of Federal Regulations: Flammable liquid 12.2 MAS Hazard Rating for Bulk Weber Transportation: Category Rating Fire 3 Health Vapor Irritant 1 Liquid or Solid Irritant 1 Poisons 2 Water Pollution Human Toxicity 1 Aquatic Toxicity 2 Aesthetic Effect 2 Rescrivity Other Chemicals 0 Water 0 Scil-Reaction 0 12.3 MFPA Hizard Clessifications; Category Clessifications Hammability (Red) 3 Reactivity (Velow) 0	= 60—199°C = 333—472°K 13.4 Preezing Point: Not pertinent 13.5 Critical Temperature: Not pertinent 13.6 Critical Pressure: Not pertinent 13.7 Specific Gravity: 0.71—0.747 at 20°C ((iquid) 13.8 Liquid Surface Tension: 19—23 dynes/cm = 0.019—0.031 N/m at 20°C 13.9 Liquid-Water interfacial Yension: 49—31 dynes/cm = 0.049—0.051 N/m at 20°C 13.10 Vapor (Gae) Specific Gravity: 3.4 13.11 Ratio of Specific Heets of Vapor (Gae): (cs.) 1.054 13.12 Latent Heet of Vaporization: 130—150 Rev/b = 71—31 cs/g = 3.0—3.4 X IO*J/kg 13.13 Heet of Combustion: -12,720 Res/b = -10,400 cs/g = -43.51 X IO*J/kg 13.14 Heet of Decomposition: Not pertinent 13.15 Heet of Polymerization: Not pertinent 13.16 Heet of Polymerization: Not pertinent

NOTES

(Constraint on pages 5 and 6)

TETRAETHYL LEAD

6. FIRE HAZAROS 8. WATER POLLUTION 6.1 Flash Point: 200°F C.C.; 185°F O.C. 8.1 Aquatic Toxicity: Oily liquid Colorless, but generally dyed red Fruity odor TEL Land tetroothyl 0.20 mg/l /96 hr/bluegill/TLm/fresh water 6.2 Flammable Limits in Air: Data not available 8.2 Waterlowi Toxicity: Data not available 6.3 Fire Extinguishing Agents: Water, foam. Einka in water, Poisonous, flam able vapor is produ dry chemical, or carbon dioxide 8.3 Biological Oxygen Demand (BOD): 6.4 Fire Extinguishing Agenta Not to be Used: Data not available AVOID CONTACT WITH LIQUID AND VAPOR. Keep people away. Ween googles, self-contained breathing appearates, and rubber overclothing (section) glowes). Stop discharge if possible. Call fire department. Stay upwind and sex water spray to "knock down" vaper. Isoular and remove discharged maserial. Notify local health and pollution control agencies. Not pertinent 8.4 Food Chain Concentration Potential: Data not available Special Hazards of Combustion Products: Toxic gases are acadrated in fires. 6.6 Behavior in Fire: May explode in fires. 6.7 Ignition Temperature: Decomposes above 230° F Combustible.

POISONOUS GASES ARE PRODUCED IN FIRE.

Containers any explode in first.

Vapor may explode if ignited in an enciosed area.

Were pugits, self-contained breathing apparatus, and rubber overciothing (including glows).

Combat first from behind berrier or protected location.

Ploud discharge area with water.

Estinguish with water, de, chemical, foam, or carbon dioxide.

Cool exposed containers with water. 6.8 Electrical Hazard: Not pertinent 9. SELECTED MANUFACTURERS 6.9 Surning Rate: Data not available E. I. duPont de Nemours & Co., Inc. Fire Petroleum Chemicals Division Antioch, Calif. 94509 2. Ethyl Corp. Industrial Chemicals Division 151 Florida St. Batos Rouge, La. 70801 CALL FOR MEDICAL AID 7. CHEMICAL REACTIVITY PPG Industries, Inc. VAPOR POSSONOUS IF INHALED OR IF SKIN IS EXPOSED. Houston Chemical Co. Dvision 7.1 Reactivity with Water: No reaction Beaumont, Tex. 77704 7.2 Reactivity with Common Materials: Rust to trem ar. riking has stopped, give artificial respiration, riking is difficult, give oxygen. and some metals cause decomposition. LIQUED
POISONOUS IF SWALLOWED OR IF SKIN IS EXPOSED.
Will bear eyes.
Remove contaminated clothing and shoes.
Flush effected stress with plenty of water.
Fin NEYES, hold eyelith open and flush with plenty of water.
IF SWALLOWED and viction is CONSCIOUS, have victim drink water or milk and have victim in shoots womiting.
IF SWALLOWED and victim is UNCONSCIOUS OR HAVING CONVULSIONS, do nothing except keep victim warms. 7.3 Stability During Transport: Stable below 230 °F. At higher temperatures, may detonate or explode when confined. Exposure 7.4 Neutrelizing Agents for Acids and Caustics: Not pertinent 16. SHIPPING INFORMATION Polymerization: Not pertinent 10.1 Grades or Purity: Technical 7.6 Inhibitor of Polymerization: Not pertinent 10.2 Storage Temperature: Ambi 10.3 Inert Atmosphere: No requirement 10.4 Venting: Pressure-vacuum HARMFUL TO AQUATIC LIFE IN VERY LOW CONCENTRATIONS.
May be dangeroos if it enters water intakes.
Notify local health and wildlife officials.
Notify operators of nearby water intakes. Water **Pollution** 2. LABELS 1. RESPONSE TO DISCHARGE 11. HAZARD ASSESSMENT CODE 13. PHYSICAL AND CHEMICAL PROPERTIES 13.1 Physical State at 15°C and 1 atm: Liquid -CO 445-81 13.2 Molecular Weight: 323.44 Issue warning-poison. A-X-Y POISON 13.3 Bolling Point at 1 attr: Decomposes Restrict access 13.4 Freezing Point -215°F = -137°C = 136°K Chemical and physical treatment PRESENT 12. HAZARD CLASSIFICATIONS 13.5 Critical Temperature: Not pertinent 13.6 Critical Procesure: Not pertinent 12.1 Code of Federal Regulation 4. ORSERVABLE CHARACTERISTICS 3. CHEMICAL DESIGNATIONS Poisonous liquid or solid. Class B 15.7 Specific Gravity: 1.59 at 20°C (liquid) 4.1 Physical State (as shipped): Liquid 3.1 Synonyma: Lead tetracthyl 12.2 NAS Hazard Rating for Bulk Water 13.6 Liquid Surface Tensis 3.2 Coast Guard Competibility Cl 4.2 Color: Dyed red or other distinctive color. Transportation: Not listed (est.) 40 dynes/cm = 0.04 N/m at 20°C Special class 4.3 Odor: Sweet 12.3 MFPA Hazard Classifications: 13.9 Liquid-Water Interfacial Ter mical Fermula: Pb(C₂H₃)₆ (est.) 40 dynas/cm = 0.04 N/m at 20°C Category Ch (BICO/United Nations Numerical 3.4 Health Hazard (Blue) 3 13.10 Vapor (Ges) Specific Gravitic Designation: 6.1/1649 Not pertinent Flammability (Red) Reactivity (Yellow) 13.11 Ratio of Specific Heats of Vapor (Ges): Not pertinent 13.12 Latent Heat of Vaporization Not pertinent 13.13 Heat of Combusties: (cst.) =7,870 Btu/tb = -4,380 csl/g = -183 × 10° J/kg 5. HEALTH HAZARDS nt: Organic vapor type canister face mask for short periods: ctive Equips 13.14 Heat of Decomposition: Not pertinent air line type for longer periods; acoprene-coated, liquid-proof shield; white or light-colored clothing; rubber shoes or boots. ene-coated, liquid-proof gloves; protective goggles or face 13.15 Heat of Solutions Not pertinent une Following Exposure: Increased urinary output of lead. If a large degree of absorption 13.16 Heat of Polymerization: Not pertinen from inhalstion or skin contact. may cause insormals, excitability, delirium, coma and death. Do not confuse with inorganic lead. ent for Exposure: Remove victim from contaminated area and consult physician immediately. INGESTION: induce vomiting. SKIN: wash immediately with kerosene or similar petroleum distillate followed by soap and water. 5.4 Toxicity by Inhelation (Threshold Limit Value): 0.1 mg/m³ Rhort-Term toheletion Limits: Data not available 5.5 (Concinued on pages 5 and 6) 5.6 Toxicity by Ingestion: Data not available 6.7 Late Toxicity: Lead poisoning MOTES Vapor (Gas) britant Cheracteristics: Vapors cause a slight smerting of the eyes or respiratory system if present in high concentrations. The effect is temporary. 5.8 Liquid or Solid irritant Characteristics: Causes smarting of the skin and first-degree burns on short exposure; may cause secondary burns on long exposure. 5.10 Odor Threshold: Data not available

Occupational Health Guideline for Tetraethyl Lead

INTRODUCTION

This guideline is intended as a source of information for employees, employers, physicians, industrial hygienists, and other occupational health professionals who may have a need for such information. It does not attempt to present all data; rather, it presents pertinent information and data in summary form.

SUBSTANCE IDENTIFICATION

- Formula: Pb(C2H5)4
- Synonyms: TEL; lead tetraethyl; motor fuel antiknock compound
- Appearance and odor: Colorless liquid (or dyed red, orange, or blue) with a slight musty odor.

PERMISSIBLE EXPOSURE LIMIT (PEL)

The current OSHA standard for tetraethyl lead is 0.075 milligrams of tetraethyl lead per cubic meter of air (mg/m³) averaged over an eight-hour work shift. The American Conference of Governmental Industrial Hygienists has recommended that the permissible exposure limit be changed to 0.1 mg/m³. The American Conference of Governmental Industrial Hygienists has recommended for tetraethyl lead a Threshold Limit Value of 0.1 mg/m³ with a skin notation.

HEALTH HAZARD INFORMATION

Routes of exposure

Tetraethyl lead can affect the body if it is inhaled, comes in contact with the eyes or skin, or is swallowed. It may readily enter the body through the skin.

· Effects of overexposure

The absorption by humans of a sufficient quantity of tetraethyl lead either briefly at a high rate or for prolonged periods at a lower rate may cause intoxication. The onset of symptoms may be delayed for up to eight days after termination of exposure. The milder toxic effects are difficulty in sleeping, tiredness, wild

dreams, anxiety, trembling, spasms, slow heart beat, low body temperature, paleness, nausea and loss of appetite. More severe intoxication causes episodes of disorientation, hallucinations, grimacing, and intense activity which requires that the person be restrained. These episodes may convert into manic or violent convulsive seizures which may end in unconsciousness or death. Tetraethyl lead may cause irritation of the eyes. Fetal damage may occur from exposure of the mother to tetraethyl lead, by analogy to methyl mercury.

· Reporting signs and symptoms

A physician should be contacted if anyone develops any signs or symptoms and suspects that they are caused by exposure to tetraethyl lead.

• Recommended medical surveillance

The following medical procedures should be made available to each employee who is exposed to tetraethyl lead at potentially hazardous levels:

1. Initial Medical Examination:

- —A complete history and physical examination: The purpose is to detect pre-existing conditions that might place the exposed employee at increased risk, and to establish a baseline for future health monitoring. Persons with a history of mental disorders or hypotension would be expected to be at increased risk from exposure. Examination of the central nervous system and the cardiovascular system should be stressed.
- —Urinalysis: Normal kidney function is considered necessary for biologic monitoring. A urinalysis should be obtained to include at a minimum specific gravity, albumin, glucose, and a microscopic on centrifuged sediment. The concentration of lead should be determined. Urine specimens with a specific gravity less than 1.020 should be discarded and another sampled obtained.
- 2. Periodic Medical Examination: The aforementioned medical examinations should be repeated on an annual basis, except that the determination of lead in the urine should be repeated quarterly.
- Summary of toxicology

Tetraethyl lead vapor affects the nervous system and

These recommendations reflect good industrial hygiene and medical surveillance practices and their implementation will assist in achieving an effective occupational health program. However, they may not be sufficient to achieve compliance with all requirements of OSHA regulations.

U.S. DEPARTMENT OF HEALTH AND HUMAN SERVICES
Public Health Service Centers for Disease Control
National Institute for Occupational Safety and Health

U.S. DEPARTMENT OF LABOR
Occupational Safety and Health Administration

causes mental aberrations including psychosis, mania, and convulsions. Of 41 female Swis ce which survived for 36 weeks after a single subcutaneous injection of 0.6 mg, 5 developed malignant lymphomas during the next 15 weeks; the significance of these data cannot be evaluated, because this tumor occurs spontaneously with a variable incidence in the mouse strain used. The absorption by humans of a sufficient quantity of tetraethyl lead, either briefly at a high rate (100 mg/m³ for 1 hour) or for prolonged periods at a lower rate, causes acute intoxication; chronic intoxication has not been observed. The onset of symptoms may be delayed for up to 8 days after termination of exposure. The milder manifestations of intoxication are insomnia, lassitude, lurid dreams, dream-like waking states of anxiety, tremor, hyperreflexia, spasmodic muscular contractions, bradycardia, hypotension, hypothermia, pallor, nausea, and anorexia. More severe intoxication causes recurrent or nearly continuous episodes of disorientation, hallucinations, facial contortions, and intense hyperactivity which requires that the individual be restrained. Such episodes may convert abruptly into manic or violent convulsive seizures which may terminate in coma and death. During intoxication there is a striking elevation of the rate of excretion of lead in the urine but only a negligible or slight elevation of the concentration of lead in the blood. In severe intoxication, the urine lead is rarely less than 350 ug/l of urine, while the blood lead is rarely more than 50 ug/100 g of blood. There is also a total absence of morphological or chemical abnormalities in the erythrocytes, in sharp contrast to intoxication caused by inorganic lead. In a mortality study of 592 workers, the mean exposure time was 17.9 years, and urinary lead levels during this period did not exceed 180 ug/l; the incidence of death in this group and in a control group of employees was less than that expected in the general population, and there were no peculiarities in the specific causes of death in either group. In a similar study of a different cohort of these exposed workers, there were no significant health differences when compared with a control group. Although tetraethyl lead may be irritating to the eyes, this effect is considered insignificant when compared with the effects on the central nervous system.

CHEMICAL AND PHYSICAL PROPERTIES

Physical data

- 1. Molecular weight: 323.4
- 2. Boiling point (760 mm Hg): Decomposes above 100 C (212 F)
 - 3. Specific gravity (water = 1): 1.65
- 4. Vapor density (air = 1 at boiling point of tetraethyl lead): 8.6
 - 5. Melting point: -138 to -130 C (-216 to -202 F)
 - 6. Vapor pressure at 20 C (68 F): 0.2 mm Hg
- 7. Solubility in water, g/100 g water at 20 C (68 F): Insoluble
 - 8. Evaporation rate (butyl acetate = 1): Data not

available

Reactivity

- 1. Conditions contributing to instability: Temperatures above 100 C (212 F) cause decomposition and development of pressure that may cause containers to burst.
- 2. Incompatibilities: Contact with strong oxidizers, such as sulfuryl chloride or potassium permangonate, may cause fires and explosions.
- 3. Hazardous decomposition products: Toxic airborne substances (such as lead fumes and carbon monoxide) may be released in a fire involving tetraethyl lead.
- 4. Special precautions: Tetraethyl lead will attack some forms of plastics, rubber, and coatings.

Flammability

- 1. Flash point: 93 C (200 F) (closed cup)
- 2. Autoignition temperature: Data not available
- 3. Flammable limits in air, % by volume: Data not available
- 4. Extinguishant: Dry chemical, foam, carbon dioxide

Warning properties

- 1. Odor Threshold: No quantitative information is available concerning the odor threshold of tetraethyl lead. The AIHA *Hygienic Guide* states that this substance "has a characteristic sweetish odor, but the intensity of the odor is not adequate to warn of hazardous concentrations."
- 2. Eye Irritation Level: Grant states that "concerning local effects on the eye from direct contact, there was recorded by Leake in 1926 a strange account of a contamination of the eyes from a splash of gasoline containing tetraethyl lead, after which the patient was said to have been unable to see for three-fourths of an hour. In the course of two months the patient was reported improved and was found to have no corneal or ophthalmoscopic abnormality, but was thought to have slight mydriasis, photophobia, and contraction of the visual field. Very likely the initial difficulty in seeing was due to smarting sensation in the eyes and blepharospasm. The evidence of later eye abnormality in this case seems quite indefinite and questionable.

"I have tested high-test gasoline containing tetraethyl lead by dropping on rabbit eyes, and have found it to cause immediate pain and blepharospasm lasting several minutes. When the application was repeated ten times in the course of five minutes under local anesthesia, it produced conjunctival hyperemia and moderate flocculent discharge, but no damage to cornea or conjunctiva."

3. Evaluation of Warning Properties: Since there is no quantitative information relating warning properties to air concentrations of tetraethyl lead, this substance is treated as a material with poor warning properties.

MONITORING AND MEASUREMENT PROCEDURES

... • General

Measurements to determine emple exposure are best taken so that the average eight-hour exposure is based on a single eight-hour sample or on two four-hour samples. Several short-time interval samples (up to 30 minutes) may also be used to determine the average exposure level. Air samples should be taken in the employee's breathing zone (air that would most nearly represent that inhaled by the employee).

Method

An analytical method for tetraethyl lead is in the NIOSII Manual of Analytical Methods, 2nd Ed., Vol. 4, 1978, available from the Government Printing Office, Washington, D.C. 20402 (GPO No. 017-033-00317-3).

RESPIRATORS

- · Good industrial hygiene practices recommend that engineering controls be used to reduce environmental concentrations to the permissible exposure level. However, there are some exceptions where respirators may be used to control exposure. Respirators may be used when engineering and work practice controls are not technically feasible, when such controls are in the process of being installed, or when they fail and need to be supplemented. Respirators may also be used for operations which require entry into tanks or closed vessels, and in emergency situations. If the use of respirators is necessary, the only respirators permitted are those that have been approved by the Mine Safety and Health Administration (formerly Mining Enforcement and Safety Administration) or by the National Institute for Occupational Safety and Health.
- In addition to respirator selection, a complete respiratory protection program should be instituted which includes regular training, maintenance, inspection, cleaning, and evaluation.

PERSONAL PROTECTIVE EQUIPMENT

- Employees should be provided with and required to use impervious clothing, gloves, face shields (eight-inch minimum), and other appropriate protective clothing necessary to prevent any possibility of skin contact with undiluted liquid tetraethyl lead or solutions containing more than 1.06 milliliters per liter (4 milliliters per gallon).
- Clothing contaminated with undiluted liquid tetraethyl lead or solutions containing more than 1.06 milliliters per liter (4 milliliters per gallon) should be placed in closed containers for storage until it can be discarded or until provision is made for the removal of tetraethyl lead from the clothing. If the clothing is to be laundered or otherwise cleaned to remove the tetraethyl lead, the person performing the operation should be informed of tetraethyl lead's hazardous properties.
- If employees' clothing has had any possibility of being contaminated with undiluted liquid tetraethyl

lead or solutions containing more than 1.06 milliliters per liter (4 millioners per gallon), employees should change into uncommunated clothing before leaving the work premises.

- Non-impervious clothing which becomes contaminated with undiluted liquid tetraethyl lead or solutions containing more than 1.06 milliliters per liter (4 milliliters per gallon) should be removed immediately and not reworn until the tetraethyl lead is removed from the clothing.
- Employees should be provided with and required to use splash-proof safety goggles where liquid tetraethyl lead may contact the eyes.

COMMON OPERATIONS AND CONTROLS

The following list includes some common operations in which exposure to tetraethyl lead may occur and control methods which may be effective in each case:

Operation

Liberation during manufacture in preparation of antiknock agents for fuels

Liberation during formulation at petroleum refinery for use as an antiknock agent

Controls

Process enclsoure; local exhaust ventilation; personal protective equipment

Local exhaust ventilation; total enclosure; personal protective devices

EMERGENCY FIRST AID PROCEDURES

In the event of an emergency, institute first aid procedures and send for first aid or medical assistance.

Eye Exposure

If liquid tetraethyl lead or strong concentrations of tetraethyl lead vapors get into the eyes, wash eyes immediately with large amounts of water, lifting the lower and upper lids occasionally. Get medical attention immediately. Contact lenses should not be worn when working with this chemical.

Skin Exposure

If liquid tetraethyl lead or strong concentrations of tetraethyl lead vapors get on the skin, immediately rinse the contaminated skin with kerosene or similar petroleum products, if readily available, then wash the skin using soap or mild detergent and water. If liquid tetraethyl lead or strong concentrations of tetraethyl lead vapors penetrate through the clothing, remove the clothing immediately and first rinse the skin with kerosene or similar petroleum products, if readily available, then wash the skin using soap or mild detergent and water. Get medical attention immediately.

Breathing

If a person breathes in large amounts of tetraethyl lead, move the exposed person to fresh air at once. If breathing has stopped, perform artificial respiration. Keep the affected person warm and at rest. Get medical attention as soon as possible.

Swallowing

When tetraethyl lead has been swallowed and the person is conscious, give the person large quantities of water immediately. After the water has been swallowed, try to get the person to vomit by having him touch the back of his throat with his finger. Do not make an unconscious person vomit. Get medical attention immediately.

• Rescue

Move the affected person from the hazardous exposure. If the exposed person has been overcome, notify someone else and put into effect the established emergency rescue procedures. Do not become a casualty. Understand the facility's emergency rescue procedures and know the locations of rescue equipment before the need arises.

SPILL, LEAK, AND DISPOSAL PROCEDURES

- Persons not wearing protective equipment and clothing should be restricted from areas of spills or leaks until cleanup has been completed.
- If tetraethyl lead is spilled or leaked, the following steps should be taken:
- 1. Ventilate area of spill or leak.
- 2. For small quantities, absorb on paper towels. Evaporate in a safe place (such as a fume hood). Allow sufficient time for evaporating vapors to completely clear the hood ductwork. Burn the paper in a suitable location away from combustible materials. Large quantities can be collected and atomized in a suitable combustion chamber equipped with an appropriate effluent gas cleaning device.
- Waste disposal methods:

Tetraethyl lead may be disposed of:

- 1. By absorbing it in vermiculite, dry sand, earth or a similar material and disposing in a secured sanitary landfill.
- 2. By atomizing in a suitable combustion chamber equipped with an appropriate effluent gas cleaning device.

REFERENCES

• American Conference of Governmental Industrial Hygienists: "Tetraethyl Lead," Documentation of the

Threshold Limit Values for Substances in Workroom Air (3rd ed., 2nd printing Lincinnati, 1974.

- American Industrial Hygiene Association: "Tetraethyl Lead," *Hygienic Guide Series*, Detroit, Michigan, 1963.
- Baskin, A. D. (ed.): Handling Guide for Potentially Hazardous Commodities, Railway Systems and Management Association, Chicago, 1972.
- Christensen, H. E., and Luginbyhl, T. L. (eds.): NIOSH Toxic Substances List, 1974 Edition, HEW Publication No. 74-134, 1974.
- Epstein, S. S., and Mantel, N.: "Carcinogenicity of Tetraethyl Lead," *Experientia*, 24:580-581, 1968.
- Fleming, A. J.: "Industrial Hygiene and Medical Control Procedures Manufacture and Handling of Organic Lead Compounds," Archives of Environmental Health, 8:266-270, 1964.
- Grant, W. M.: Toxicology of the Eye (2nd ed.), C. C. Thomas, Springfield, Illinois, 1974.
- International Agency for Research on Cancer: Some Inorganic and Organo-Metallic Compounds, Vol. 2 of IARC Monographs on the Evaluation of the Carcinogenic Risk of Chemicals to Man, Lyon, France, 1973.
- International Labour Office: Encyclopedia of Occupational Health and Safety, McGraw-Hill, New York, 1974.
- Registry of Toxic Effects of Chemical Substances, U.S. Department of Health, Education, and Welfare, Rockville, Maryland, June 1975.
- Robinson, T. R.: "The Health of Long Service Tetraethyl Lead Workers," *Journal of Occupational Medi*cine 18:31-40, 1976.
- Robinson, T. R.: "Twenty-Year Mortality of Tetraethyl Lead Workers," *Journal of Occupational Medicine*, 16:601-605, 1974.
- Sanders, L. W.: "Tetraethyllead Intoxication," Archives of Environmental Health, 8:270-277, 1964.
- Stauden, A. (ex. ed.): Kirk-Othmer Encyclopedia of Chemical Technology (2nd ed.), Interscience, New York, 1972.

RESPIRATORY PROTECTION FOR TETRAETHYL LEAD

Condition	Minimum Respiratory Protection* Required Above 0.075 mg/m³
Vapor Concentration	
0.75 mg/m³ or less	Any supplied-air respirator.
	Any self-contained breathing apparatus.
3.75 mg/m³ or less	Any supplied-air respirator with a full facepiece, helmet, or hood.
•	Any self-contained breathing apparatus with a full facepiece.
40 mg/m³ or less	A Type C supplied-air respirator operated in pressure-demand or other positive pressure or continuous-flow mode.
Greater than 40 mg/m³** or entry and escape from unknown concentrations	Self-contained breathing apparatus with a full facepiece operated in pressure- demand or other positive pressure mode.
	A combination respirator which includes a Type C supplied-air respirator with a full facepiece operated in pressure-demand or other positive pressure or continuous-flow mode and an auxiliary self-contained breathing apparatus operated in pressure-demand or other positive pressure mode.
Fire Fighting	Self-contained breathing apparatus with a full facepiece operated in pressure- demand or other positive pressure mode.
Escape	Any gas mask providing protection against organic vapors.
	Any escape self-contained breathing apparatus.

^{*}Only NIOSH-approved or MSHA-approved equipment should be used.

^{**}Use of supplied-air suits may be necessary to prevent skin contact while providing respiratory protection from airborne concentrations of tetraethyl lead; however, this equipment should be selected, used, and maintained under the immediate supervision of trained personnel. Where supplied-air suits are used above a concentration of 40 mg/m³, an auxiliary self-contained breathing apparatus operated in positive pressure mode should also be worn.

LEAD PEROXIDE. See lead dioxide.

LEAD PHENATE. Yellowish to grayish-white powder. Pb(OH)OC₆H₅, mw: 317.28.

THR = See lead compounds and phenol.

LEAD-o-PHOSPHATE. Hexagonal, colorless or white powder. Pb₃(PO₄)₂, mw: 811.59, mp: 1014, d: 6.9-7.3.

THR = A poison. See also lead compounds.

LEAD-m-PHOSPHATE. Colorless crystals. Pb(PO₃)₂, mw: 365.17, mp: 800°.

THR = See lead compounds. An exper (\pm) carc. [3, 9]

LEAD-o-PHOSPHITE. White powder. PbHPO₃, mw: 287.20, mp: decomp.

THR = See lead compounds and phosphites. A fiber drum of it self-ignited. [19]

LEAD PICRATE. Yellow crystals. Pb($C_6H_2O_7$)₂ · H_2O , mw: 681.43, mp: $-H_2O$ @ 130°, bp: explodes, d: 2.831 @ 20°.

THR = See lead compounds and picric acid.

LEAD PROTOXIDE. See litharge.

LEAD PYROARSENATE. See lead arsenates.

LEAD PYROPHOSPHATE. White crystals. Pb₂P₂O₇, mw: 588.38, mp: 824°, d: 5.8.

THR = See lead compounds and phosphates.

LEAD RED. See lead oxide.

LEAD RESINATE. Yellowish-white paste.

 $Pb(C_{20}H_{29}O_2)_2$, mw: 810.07.

THR = See lead compounds.

Fire Hazard: Mod, when exposed to heat or flame. Disaster Hazard: See lead.

LEAD SELENATE. White crystals. PbSeO₄, mw: 350.17, mp: decomp. d: 6.37.

THR = See lead compounds and selenium compounds.

LEAD SELENIDE. Syn: clausthalite. Cubic crystals. PbSe, mw: 286.17, mp: 1065°, d: 8.10 @ 15°.

THR = See lead and selenium compounds.

Fire Hazard: Mod, in the form of dust when exposed to flame or by chemical reaction with moisture to evolve the hydrides. See also hydrogen selenide.

Explosion Hazard: Slight, by chemical reaction with moisture. See also hydrogen selenide.

Disaster Hazard: See lead and selenium.

LEAD SILICATE. See lead-m-silicate.

LEAD-m-SILICATE. Syn: alamosite. White crystalline powder. PbSiO₃, mw: 283.27, mp: 766°, d: 6.49. THR = See lead compounds.

LEAD STEARATE. White powder. Pb(C₁₈H₃₅O₂)₂, mw: 774.1, mp: 115.7°.

THR = See lead compounds.

LEAD STYPHNATE: See lead trinitroresorcinate.

LEAD SULFATE. Syn: anglisite. White rhombic crystals. PbSO₄, mw: 303.27, mp: decomp @ 1000°, d: 6.2.

Acute tox data: ip LD₅₀ (guinea pig) = 300 mg/kg. [3] THR = HIGH via ip route. A strong irr to skin, eyes and mu mem. See lead compounds. Violent reaction with K. [19]

LEAD SULFIDE. Syns: galena, plumbous sulfide. Silvery, metallic crystals or black powder. PbS, mw: 239.27, mp: 1114°, bp: 1281° (sublimes), d: 7.5, vap. press: 1 mm @ 852°.

Acute tox data: ip LD_{LO} (rat) = 1847 mg/kg. [3] THR = MOD via ip route. See also sulfides and lead compounds. Violent reaction with ICl, H₂O₂. [19]

LEAD SULFITE. White powder. PbSO₃, mw: 287.28. THR = See lead compounds and sulfites.

LEAD SULFOCYANATE. Syn: lead thiocyanate.

Monoclinic white crystals. Pb(SCN)₂, mw: 323.37, d: 3.82.

THR = See lead compounds and thiocyanates.

LEAD TARTRATE. White crystalline powder.

PbC₄H₄O₆, mw: 355.28, d: 2.54 @ 19°.

Acute tox data: ip LD_{LO} (rat) = 1200 mg/kg. [3]

THR = MOD via ip route. See lead compounds.

LEAD TELLURIDE. Syn: altaite. White cubic crystals. PbTe, mw: 334.82, mp: 917°, d: 8.16.

THR = See lead compounds and tellurium compounds.

LEAD TETRAACETATE. Colorless to faintly pink monoclinic crystals. Pb(CH₃COO)₄, mw: 443.39, mp: 175°, d: 2.228 @ 17°.

THR = See lead compounds.

LEAD TETRAAZIDE. Pb(N₃)₄, mw: 355.3.

THR = Very unstable. [19] Probably HIGH toxicity. See also lead compounds and azides.

LEAD TETRACHLORIDE. Yellow, oily liquid. PbCl₄, mw: 349.04, mp: -15°, bp: explodes @ 105°, d: 3.18 @ 0°.

THR = See lead and hydrochloric acid.

LEAD TETRAETHYL. Syn: TEL. Colorless, oily liquid, pleasant characteristic odor. Pb(C₂H₅)4, mw: 323.5, mp: 125°-150°, bp: 198°-202° with decomp. d: 1.659 @ 18°, vap. press: 1 mm @ 38.4°, flash p: 200° F.

Acute tox data: Oral LD_{LO} (rat) = 17 mg/kg; inhal LC₅₀ (rat) = 6 ppm; pa LD₅₀ (rat) = 15 mg/kg; dermal LD_{LO} (dog) = 500 mg/kg; dermal LD_{LO} (guinea pig) = 990 mg/kg. [3]

L

THR = HIGH via oral, inhal, pa and dermal routes.

This material is a powerful poison and a solvent for fatty materials. It has some solvent action on rubber as well. The fact that it is a lipoid sol-

For Countermeasure Information and Abbreviations see the Directory at the Beginning of this Section.

c crys-10°, d:

kg. [3] n, eyes l reac-

le. Sil-, mw: 5, vap.

اد ا lead . [19]

:87.28.

.37, d:

3] is. ystals.

com-

/ pink 9, mp:

xicity.

PbCl₄, 15°, d:

ily liq-, mw:

:comp. lash p:

; inhal g; derguinca

routes.
solvent
action
iid sol-

vent makes it an industrial hazard, because it can cause intoxication not only by inhal but also by absorption through the skin. Decomp when exposed to sunlight or allowed to evaporate; forms triethyl lead, which is also a poisonous compound. as one of its decomp products. This liquid lead compound, when handled in undiluted form or concentrated solution as when it is manufactured or in the plants where it is mixed with gasoline, may cause lead exposure intoxication by coming in contact with the skin. Therefore, any open receptacle which contains these liquids in high conc or any container, article of clothing, or any other object which is not kept clean, particularly in contact with this material, may subject personnel to serious lead exposure. An exper (±) carc. [3, 6] A common air

Fire Hazard: Mod, when exposed to heat, flame or oxidizers.

Disaster Hazard: Dangerous; see lead; can react vigorously with oxidizing materials.

To Fight Fire: Dry chemical, CO₂, mist, foam.

LEAD TETRAFLUORIDE. Syn: plumbic fluoride. White crystals, reacts with moisture. PbF₄, mw: 283.2, d: 6.7, mp: 600° (approx).

THR = See lead compounds and fluorides.

LEAD TETRAMETHYL. Syn: tetramethyl lead. Colorless liquid. Pb(CH₃)₄, mw: 267.33, mp: -18°F, lel = 1.8%, bp: 110°, d: 1.99, vap. d: 9.2, flash p: 100°F.

Acute tox data: Oral LD₅₀ (rat) = 109 mg/kg; pa LD₅₀ (rat) = 105 mg/kg; ip LD_{LO} (rat) = 73 mg/kg; iv LD_{LO} (rabbit) = 90 mg/kg. [3]

THR = HIGH via oral, pa, ip and iv routes. See also lead and lead tetraethyl. An exper (±) carc. [3, 6] Fire Hazard: Dangerous, when exposed to heat, flame or oxidizers.

Explosion Hazard: Mod, in the form of vapor when exposed to flame.

Disaster Hazard: Dangerous; see lead; can react vigorously with oxidizing materials.

la Fight Fire: Water, foam, CO2, dry chemical.

LEAD THIOCYANATE. See lead sulfocyanate.

LEAD THIOSULFATE. Syn: lead hyposulfite. White crystals. PbS₂O₃, mw: 319.33, mp: decomp, d: 5.18. THR = See lead compounds.

Disaster Hazard: Dangerous; See lead and SO_x.

LEAD-m-TITANATE. Pale yellow solid. PbTiO₃H, mw: 304.1, d: 7.52.

Acute tox data: ip LD₅₀ (rat) = 2000 mg/kg. [3] THR = MOD via ip route. See also lead and titanium compounds.

LEAD TRINITRORESORCINATE. Syn: lead styphnate. Orange-yellow, monoclinic crystals.

C₆H(NO₂)₃(O₂Pb), mw: 450.30, mp: explodes @ 311°, d: 3.1-2.9.

THR = See lead compounds and nitrates. Very sensitive explosive. It is shock-sensitive and has detonated spont when dry. [19]

Fire Hazard: See nitrates and explosives, high.

Explosion Hazard: Severe, when heated.

Disaster Hazard: Dangerous; explodes at 311°.

LEAD TUNGSTATE. Syn: lead wolframate. Yellowish powder. PbWO₄, mw: 455.13, d: 8.235.

THR = See lead compounds and tungsten compounds.

LEAD-m-VANADATE. Yellow powder. Pb(VO₃)₂, mw: 405.11.

THR = See lead and vanadium compounds.

LEAD WOLFRAMATE. See lead tungstate. LEATHER.

THR = A MILD allergen. Handling "green" hides from certain parts of the world can bring about contact with anthrax spores. Furthermore, tanning can introduce materials such as chromium, formaldehyde, etc.

Fire Hazard: Slight, when exposed to heat or flame; can react with oxidizing materials.

LEATHER BLEACH.

THR = U.

Fire Hazard: Dangerous, when exposed to heat or flame.

Explosion Hazard: U.

Disaster Hazard: Mod dangerous; when heated to decomp, emits toxic fumes; can react with oxidizing materials.

To Fight Fire: Foam, CO₂, dry chemical.

LEATHER DRESSING. Flash p: < 80°F.

THR = U. Some dressings may act as irr or allergens. Fire Hazard: Dangerous, when exposed to heat or flame; can react with oxidizing materials.

Explosion Hazard: U.

To Fight Fire: Foam, CO₂, dry chemical.


LECITHIN. The lecithins are mixtures of diglycerides of fatty acids linked to the choline ester of phosphoric acid. They are classified as phosphoglycerides or phosphatides.

CH₂(R)CH(R')CH₂OPO(OH)O(CH₂)₂N(OH)(CH₃)₃ where R and R' are fatty acid groups.

THR = U. Probably LOW. Used as a general purpose food additive. It is a substance which migrates to food from packaging materials. [109]

"LEDATE." See lead dimethyl dithiocarbamate. LEGAL MEDICINE. See forensic toxicology. LENACIL. See venzar.

SITE LOCATION



AGREEMENT TO ALLOW ENTRY TO PROJECT FOR ENVIRONMENTAL INVESTIGATION

	ENTRY TO PREMISES. CARO AN CO.
access t	s), as legal owner(s) of or as lessee(s) with authority to permit to the below described property, hereby knowlingly consents to and less the United States Environmental Protection Agency (EPA) or its or, Grantee, to enter upon and perform certain investigative activi-
	DESCRIPTION: Up zardous waste treatment
	STREET OR LOCATION: 500 W. M. K. 3500/ 816-732-4/17
	CITY/TOWN: No loen
	COUNTY: JOHN SON
	STATE: MO 64040
ate the above-de	OF INVESTIGATION. The purpose of the investigation is to evalu- nature and the extent of possible chemical contamination of the scribed property which may have resulted from past activities involving osal of contaminated wastes on the property or nearby property.
INVESTIG	ATIVE ACTIVITIES. The investigation activities are expected to
a.	The collecting and taking of such soil, water, air, and other samples as may be determined to be necessary by grantee. This may include entry into and sample collection from buildings and other structures on said property.
b.	The drilling of holes for subsurface investigation, in road areas, including the use of drilling rigs, trucks and other equipment as necessary; and
c.	Other actions related to the investigation of surface or sub- surface contamination from wastes deposited on the property or nearby, specifically:
	·

TERM OF AGREEMENT. The activities authorized under this agreement are expected to be completed on or before the _____ day of ______, 1983, and all rights and privileges given by Grantor(s) shall cease on that date, unless extended by subsequent agreement.

AGREPMENT NOT TO INTERFERE. Grantor(s) agrees not to interfere with any of the activities described herein, or to undertake any actions regarding the use of the property which would tend to endanger the health or welfare of the Grantee(s), or to allow others to use the property in such a manner.

RESTORATION OF PROPERTY. The Grantee agrees that, with the exception of any ground markers which may be placed on the premises to designate sampling areas, all material and equipment utilized by Grantee shall be removed from the property upon the completion of the investigations and activities authorized by this agreement.

The undersigned have read this Agreement and understand that it grants permission to the EPA or its contractors to enter the above-described premises for purposes of conducting an environmental investigation and agree to its terms and conditions.

GRANTORS & L. R. D.	10-13-83
NAME 8	DATE
NAME	DATE
Michael S. Clampas Roy WI TAT NAME	Ø 10-13-83

DETELED SAMPLE INFORMATION SET

FOR

SAMPLE NO. AKOIOI

Feb pil 2.5 How 20-40 pp FOTENTIAL SUESTANCE IN THIS Petroleum Hydroca	m SAMPLE:	Explosimeter 15%	LEL
FOTENTIAL CONCENTRATION OF S	SUESTANCE MED	IN THIS SAMPLE:	UNK
STATE OF SAMFLE IS: GAS	LIO	SOLID	5i ubra.
SUESTRATE OF THE SAMPLE IS:		AIR	WATER
SEDIMENT .		SOIL	Ollu I.
FOSSIBLE HAZARDS OF SAMPLES IGNITABLE REACTIVE	V	VOLATILE RADIDACTIVE	V COKKO!
UNKNOHN		KHUTUHUTIVE	1.1 101 or
FOTENTIAL TOXICITY OF SAMPLE	: MED	1.0H	UNK
FOSSIELE ROUTE OF TOXICITY:	INHAL	INGEST	UNK
************	*****	**************************************	KERRRRRRRR
TANALYSES REPUESTED: Priovity	Polly	art/GCM	& /metals
DETECTION LIMITS REQUESTED:	FPH -	7	V RUM
TURNAROUND TIME REQUESTED:	UEENG	į	

LIFFN 7HFF1

ERONMENTAL PROTECTION AGENCY REGION VII SURVEILLANCE AND ANALYSIS DIVISION, 25 FUNSTON ROAD, KANSAS CITY, KANSAS 65115

FLOW	DATA							
(M40) 650CO	AIR 00020	WATER 00010	PH	DO	FECAL COLI	OIL & GREASE	OTHER	OTHE
00061 (CFS)	<u></u>	00010				SAMPLER	LAB	
COLLECTION DA	"	''-	00400	DAY	TIME	NAME CODE	NO	7
	<u> </u>						<u> </u>	
COLLECTION DA	176	YR	MO	DAY	11ME	NAME CODE	NO	
				-				<u></u>
COLLECTION DA		YR :	MO	DAY	11ME	SAMPLER NAME CODE	LAB NO	
							T	1
	<u></u>					SAMPLER	LAB	_!
COLLECTION DA	16	<u> </u>	мо	DAY	TIME	NAME CODE	NO	
	<u> </u>					<u> </u>	<u></u>	
COMPOSITE SAI							LAS NO AK	5/0]
BE	GIN DATE:	YR ——	MO	DAY	TIME		LAB NO. F7	<u> </u>
1	IND DATE.	YR	mo	DAY	TIME	EQUIPMEN	T CODE	
FLOW RAT	·		MGD		OF GAL DURING	SAMPLER N	AME CODE	<u>.</u> , ,,
WATER CHEMIST		0050		50052 COM	POSITE PERIOD			***************************************
SAMPLE CO	MALTA INJER	ı	TAG COLOR		SERVATIVE	LABORATORY	1 LAB NO	
			120 00101	7 %			T	AI VESE
67 . —	٠.	l.	0			MOBILE REGION	+	ALYSES
Put JA	177		Purple		·	MOBILE REGION	+	
that Ja	יוכ		Purple		·	MOBILE REGION	P 7	SC 1979
12 m	177		Purple		·	MOBILE REGION	P 7	
Put Ju	777		Purple		·	MOBILE REGION	P 7	SC 1979
Put Ju	577		Purple			MOBILE REGION	P 7	SC 1979
Part Ju	172		Purple		·	MOBILE REGION	P 7	SC 1979
Part Ja	117		Purple			MOBILE REGION	P 7	SC 1979
Plus Ja	117		Purple			MOBILE REGION	P 7	SC 1979
Part Ja			Purple			MOBILE REGION	P 7	SC 1979
	· · · · · · · · · · · · · · · · · · ·						P 9 (scins etals
couries. Cla	mon		40/6×			SAMPLE TYES	PP 19 (etals
couries. Cla	mon	/) //	40/6×	emu e		SAMPLE TYES	PP 19 (etals
couries. Cla	mon	ار المحدد مراكب	40/6×	emium lear		SAMPLE TYES	PP 19 (etals
couries. Cla	mon	Secoly Secoly	40/6×	emium lear had previ		SAMPLE TYES	PP 19 (etals

EPA, Region YII 25 Funstan Road Kansas City, Kansas 66115 HAZARONS Receipt for Environmental Samples

	ty Name(ARO/A	N Co.	INC	
City	5 500 W	m ZIC	550c/5	640	
Permit	Number sible Offic	1 and 14		7	
kespon	SIDIE VITIC		IE REL	<u></u>	
Laboratory Sample No.	Cubitainer No.	Glass Jar	Containers DO Bottle ners per La	Bio Bottle	Description of Samples
Akolol		1			Sludge from tank bottom
					•
		-			•
		•			:
	·				•
,		:	Acknowl edge	ment	
The undersigne	d acknowledg	ge receipts	for the abo	ove described	samples pursuant to:
Section 3 Section 1	007(a) of the control	the Clean the Clean	Water Act	ion and Recov	ery Act, 42USC6927CAL
Duplicate samp Duplicate samp or his designa	les Here/wei	re not requ re not prov	uested by the rided to the	e responsible responsible	e facility representative. facility representative.
Signature and	Title of Re	esponsible	Facility Of	ficial	
Dilethy. RED					
Date of Signi	Signature	-12-83		•	Title
,				·— ·— ·	
Name and Title	of Person	Collecting	Samples		•
Multiple Signature of C	Jemes Collector	Reg. V	II TAT	,	

```
· REDLE TEST
START 10.12.20.04.
       STOP
C-R18
             99
SMPL #
FILE #
              5
           2756
REPT #
METHOD
           1044
                                                 HEIGHT
                                        MK
                             CONC
        NAME
                TIME
            TOTAL
             -9.2
LEVEL
              5.8
LEVEL
LEVEL
              5.6
             -0.8
LEVEL
 SBST TAME
ATT 12874UL
       10.12.20.08.
START
              1.44
       STOP
C-R1B
             ØØ
SMPL #
             5
FILE #
           2757
REPT #
METHOD
           1044
                                                  HEIGHT
                             CONC
                                        MK
```

1.5437

2.3343

2.0115

5.8895

58

88

76

223

HAME

Ħ

1

1

1

TIME

0.54

0.66 0.73

TOTAL

5.4498

11.9615 4.5593

3.7276 0.5699 66.2354 137

302 115 :

94 14

1672

1

2.18

2.57 3.01

3.33 3.97

TOTAL

```
C1/C2
                  TIME BAND
                                    F1/F2
                  4.5 100
                                     0
                                                             44
               END
SPL WT
CALIB
C-R18
SMPL #
              99
FILE #
PEPT #
            2754
            1044
METHOD
CLB C1
                                                      HEIGHT
         NAME
                  TIME
                                CONC
                                           MK
                  0.8
                                                         55
61
                  0.92
                  1.09
1.26
                                                         53
                                                        170
                  1.47
1.69
1.92
                                                        243
                                                        242
                                                        182
                  2.18
2.57
                                                        137
                                                        302
                  3.01
                                                        115
                  3.33
                                                         94
                                                       14
1672
                  3.97
             TOTAL.
                                 Ø
          5
ID TBL
   MAX
              14
2
  MODE
                 TIME BAND
                                   F1/F2
                                                            C1/C2
```

4.5 100

0.001052

44